



# CGA/EGA/YUV TO VGA Converter Wiring Diagram

OPTIONAL  
DOUBLE (CLONE)  
VGA OUTPUT



12 PIN  
VGA OUTPUT


BARREL JACK  
5V DC IN.  
(DO NOT USE 12V  
UNLESS ADVISED  
OTHERWISE)



TWO PIN 5V DC IN

NOT USED

EGA/CGA INPUT



UP  
MENU  
DOWN  
DOWN OR  
AUTO SCAN

INPUT SWITCH BUTTON

VGA INPUT



YPbPr Input

Retro  
ARCADE